

GREGORY S. BELL

Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER Executive Director

Division of Oil, Gas and Mining JOHN R. BAZA

Division Director

Minerals Inspection Report

Reviewed PR

	Re	port Date: 07/14/201	5		
Mine Name: : Solar Wind		Permit Number:	S/023/0061	Mine Status:	Active
Operator Name: Got Named Inc		Inspection Date:	07/09/2015	Permit Fees:	Paid
Inspector(s): Wayne Western		Inspection Time:	4:15-4:30 pm	Bond Amount:	\$9,700
Attendee(s):		Weather:	clear and warm	Bond Escalation:	04/05/2017
Inspe	ection Purpose: Routine inspection			Prior Inspection:	08/23/2012
	Clusions and Recommendations Operator reported production in 2014.	4	Tr.	valuated & Commented	Enforcement
Elements of Inspection			EV		Enforcement
1.	Permits, Revisions, Transfer, Bonds				
	Permit fee paid and bond current.				
2.	Public Safety (shafts, adits, trash, signs, highwalls)				
	Operator painted warning signs of rocks at site. mining.	BLM requires that warning s	gns are on metal o	or wood and can be remo	oved after
3.	Protection of Drainages/Erosion Control				
4.	Deleterious Material				
5.	Roads (maintenance, surfacing, dust control, safety)				
6.	Reclamation				
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts)				
8.	Soils				
9.	Revegetation				
10.	Other				

Inspector's	Signature:

 $File: \ / nrwogmfs 1/OGM/GROUPS/MINERALS/WP/M023-Juab/S0230061-SolarWind/inspections/Inspect07092015.pdf$



S/023/0061 Mine: Page 2 of 2

Inspected: 07/09/2015





Small pit that was not present during last inspection





Pad area and highwalls

Pad area and highwalls

